5

ABSTRACT

In a rotary electric machine, an armature winding comprises three first phase-windings that form a Δ -connection winding having output ends and three second phase-windings that are respectively connected in series to the output ends to form a star-connection three-phase winding having output ends connected to a rectifier unit.